

PE-10

Working At Heights

Working 6 feet above the ground cannot proceed unless ...

- fall arrest equipment is in place - guardrails, safety harness
- a proper anchor is available and mounted, preferably overhead
- a fall prevention system such as a tether or restraining system is used
- fall arrest system is properly tested prior to use



For more information on this and other **Golden Rules** go to:

<http://hse.bpweb.bp.com/goldenrules>

